

CERTIFICATE OF COMPLIANCE

Certificate Number 20190927-E68961
Report Reference E68961-20190919
Issue Date 2019-SEPTEMBER-27

Issued to: IDEC CORP
6-64 NISHIMIYAHARA 2-CHOME
YODOGAWA-KU
OSAKA 532-0004 JAPAN

**This certificate confirms that
representative samples of**

AUXILIARY DEVICES
Relay Modules, Model HR5S-C2, followed by B, D-T025, D-
T050, D-T100, D-T200, D-T400 or S

Have been investigated by UL in accordance with the
Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 508 & CAN/CSA C22.2 No. 14-18 - Industrial Control
Equipment

Additional Information: See the UL Online Certifications Directory at
<https://iq.ulprospector.com> for additional information.

This *Certificate of Compliance* does not provide authorization to apply the UL Mark. Only the UL Follow-Up
Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's
Follow-Up Services.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please
contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

